
## **Order Code**



## Machining codes:

D0 = Cut/no machining	E1F	D2F
A = Annealing	E2F	E1WF
Z = According to drawing	D1B	E2WF
E1B	D2B	E1WFF
E2B	D1F	E2WFF

See further information under section Standard End Journals.